## National Transportation Safety Board NTSB ID: ANC01LA037 Aircraft Registration Number: N36266 FACTUAL REPORT Occurrence Date: 02/16/2001 Most Critical Injury: None Occurrence Type: Accident Investigated By: NTSB ETYBO Location/Time Nearest City/Place State Zip Code Local Time Time Zone ΑK 99709 1500 AST Fairbanks Distance From Landing Facility: Direction From Airport: Airport Proximity: Off Airport/Airstrip Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft Bellanca 7GCBC Airplane Sightseeing Flight: No Air Medical Transport Flight: No

## Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On February 16, 2001, about 1500 Alaska standard time, a ski equipped Bellanca 7GCBC airplane, N36266, sustained substantial damage during landing on a frozen lake, about 15 miles south of Fairbanks, Alaska. The airplane was being operated as a visual flight rules (VFR) local area instructional flight when the accident occurred. The airplane is registered to the student pilot. The commercial certificated pilot/flight instructor, and the student pilot, were not injured. Visual meteorological conditions prevailed. A VFR flight plan was filed. The flight originated at the Fairbanks International Airport, Fairbanks, about 1400.

During a telephone conversation with the National Transportation Safety Board (NTSB) investigator-in-charge (IIC), on February 20, 2001, the flight instructor reported the accident flight was the first flight with the student. The flight departed Fairbanks with the instructor seated in the front seat. He flew to an area along the Tanana River where he had previously conducted numerous takeoff and landings. The flight instructor demonstrated a variety of aerial maneuvers, and then landed on a frozen lake. The lake was covered with about two feet of snow. The instructor performed two additional takeoff and landings and then stopped. He placed the student pilot in the front seat and got into the rear seat. The instructor had the student taxi the airplane and then perform several takeoff and landings. The flight instructor then took over the flight controls and landed at a different lake, establishing a new set of ski landing tracks in the snow. The student pilot then performed two additional takeoff and landings. On the third landing approach to the new location, the airplane was established on a normal glide path. About 2 to 4 feet above the ground, the student suddenly pushed forward on the control stick and applied almost full right rudder. The instructor was unable to prevent the airplane from colliding with the snow in a nose down attitude. The airplane nosed over and received damage to the wings, wing spars, lift struts, and vertical stabilizer.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC01LA037

Occurrence Date: 02/16/2001

AVIATION			Occurrence Type: Accident					]					
Landing Facility/Approach Information													
Airport Name			Airport	t ID:	Airport Eleva	ition . MSL		nway Used	Runwa	y Lengt	h F	Runwa	ay Width
Runway Surface Type:		'					•						
Runway Surface Condition:													
Type Instrument Approach: NONE	<u> </u>												
VFR Approach/Landing: Full Stop													
Aircraft Information													
Aircraft Manufacturer Bellanca			- 1	Model/S 7GCB						Serial   560-7	Number 73		
Airworthiness Certificate(s): Norm	al		-										
Landing Gear Type: Ski; Tailwhe	el												
Homebuilt Aircraft? No					Certified Max Gross Wt.				1650 LBS Numbe			er of Engines: 1	
				Engine Manufacturer: Model/Series: Lycoming O-320-A2B							Rated Power: 150 HP		
- Aircraft Inspection Information													
Type of Last Inspection Date				Date of Last Inspection Time			Time Si	ime Since Last Inspection				e Tota	al Time
Annual			02/1	02/10/2001				2 Hours				1648 Hours	
- Emergency Locator Transmitter (	ELT) Information												
ELT Installed? Yes	ELT Operate	ed? No	)			ELT	Aided i	in Locating Ad	cident S	ite? No			
Owner/Operator Information													
Registered Aircraft Owner			St	treet Ad	ddress 191 Rey	nolds	Rd.						
Bill L. Barney			Ci	City Fairbanks							State AK		Zip Code 99712
			St	treet Ad							<u>  AIX</u>		99712
Operator of Aircraft				Same as Reg'd Aircraft Owner									
Same as Reg'd Aircraft Owner				City						State		Zip Code	
Operator Does Business As:  Operator Designator Code:													
- Type of U.S. Certificate(s) Held: N	None												
Air Carrier Operating Certificate(s):	:												
Operating Certificate:					Operator (	Certific	cate:						
Regulation Flight Conducted Under	r: Part 91: Genera	al Aviat	tion										
Type of Flight Operation Conducted	d: Instructional												
	]	FACT	UAL F	REPOI	RT - AVIAT	ION							Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC01LA037

Occurrence Date: 02/16/2001

City	AVIAT	Occurrence Type: Accident											
On File	First Pilot Information												
Sex: M Seat Occupied: Rear Principal Profession: Police Certificate (s): Flight Instructor; Commercial; Private  Airplane Raling(s): Single-engine Land; Single-engine Sea  Rotorcraft/Gilder/LTA: None Instrument Rating(s): Airplane Instructor Rating(s): Airplane Single-engine  Type Rating/Endorsement for Accident/Incident Aircraft? No Current Biennial Flight Review? 08/27/2000  Medical Cert: Class 2 Medical Cert. Status: Valid Medical—w/ waivers/film. Date of Last Medical Exam: 08/22/2000	Name	City				5	State	Date of Birth	Age				
Carrificase(s):   Flight Instructor; Commercial; Private	On File	On File	File On F				n File	On File	47				
Airplane Rating(s): Single-engine Land; Single-engine Sea  Rotocraft/Clider/LTA: None Instrument Rating(s): Airplane Instructor Rating(s): Airplane Single-engine  Type Rating/Endorsement for Accident/Incident Aircraft? No  Current Blennial Flight Review? 08/27/2000  Medical Cert.: Class 2 Medical Cert. Status: Valid Medicalw/ walvers/lim. Date of Last Medical Exam: 08/22/2000	Sex: M Seat Occupie					Certifi	cate Nun	nber: On File					
Rotorcraft/Glider/LTA: None   Instrument Rating(s): Airplane   Instructor Rating(s): Airplane   Single-engine	Certificate(s): Flight Instructor; Commercial; Private												
Instructor Rating(s): Airplane Instructor Rating(s): Airplane Single-engine  Type Rating/Endorsement for Accident/Incident Aircraft? No Current Biennial Flight Review? 08/27/2000  Medical Cert.: Class 2 Medical Cert. Status: Valid Medicalw/ waivers/lim. Date of Last Medical Exam: 08/22/2000  - Flight Time Matrix AAAC Tristade Book Status: Valid Medicalw/ waivers/lim. Date of Last Medical Exam: 08/22/2000  - Flight Time Matrix AAAC Tristade Book Status: Valid Medicalw/ waivers/lim. Date of Last Medical Exam: 08/22/2000  - Flight Time Matrix AAAC Tristade Book Status: Valid Medicalw/ waivers/lim. Date of Last Medical Exam: 08/22/2000  - Flight Time Matrix AAAC Tristade Book Status: Valid Medicalw/ waivers/lim. Date of Last Medical Exam: 08/22/2000  - Flight Time Matrix AAAC Tristade Book Status: Valid Medical-w/ waivers/lim. Date of Last Medical Exam: 08/22/2000  - Flight Time Matrix AAAC Tristade Book Status: Valid Medical-w/ waivers/lim. Date of Last Medical Exam: 08/22/2000  - Flight Pland Flight Medical Exam: 0	Airplane Rating(s): Single-engine Land; Single-engine Sea												
Type Rating/Endorsement for Accident/Incident Aircraft? No   Current Biennial Flight Review? 08/27/2000	Rotorcraft/Glider/LTA: None												
Type Rating/Endorsement for Accident/Incident Aircraft? No   Current Biennial Flight Review? 08/27/2000	Instrument Rating(s): Airp	olane											
Medical Cert.: Class 2   Medical Cert. Status: Valid Medicalw/ waivers/lim.   Date of Last Medical Exam: 08/22/2000	Instructor Rating(s): Airp	olane Single-	engine										
- Flight Time Matrix  Al AC  This Make and Model  Stripter  Flight Command(PIC)  6020  30  6020  0  30  120  80  120  12	Type Rating/Endorsement	for Accident/Ir	ncident Aircra	ft? No			Cı	urrent Bier	nial Flig	ht Rev	iew? 08	/27/2000	
- Flight Time Matrix   No.   Image: Accordance   No.   No.	Medical Cert.: Class 2	Medica	al Cert. Status	s: Valid Med	dicalw/ wa	aivers/lim	٦.		Date o	of Last	Medical	Exam: 08/22/2	2000
- Flight Time Matrix   No.   Image: Accordance   No.   No.													
Pilot in Command(PIC)	- Flight Time Matrix	aht Timo Motrix I All A/C I mis mans I .				Night					Rotorcraft	Glider	
Instructor	Total Time	6020	30	6020	0		30	120		80			
Last 90 Days   58	Pilot In Command(PIC)						$\overline{}$		_				
Last 30 Days 35 1 35 1 35		+			0		10	(	)	0			
Seatbelt Used? Yes  Shoulder Harness Used? Yes  Toxicology Performed? No  Second Pilot? Yes  Flight Plan/Itinerary  Type of Flight Plan Filed: VFR  Departure Point Fairbanks  AK PAFA  Airport Identifier  Local Flight  Type of Clearance: None  Type of Airspace: Class G  Weather Information  Source of Briefing: Flight Service Station  Method of Briefing: In Person	•	+											
Seatbelt Used? Yes Shoulder Harness Used? Yes Toxicology Performed? No Second Pilot? Yes  Flight Plan/Itinerary  Type of Flight Plan Filed: VFR  Departure Point State Airport Identifier Departure Time Time Zone Fairbanks AK PAFA 1400 AST  Destination State Airport Identifier Local Flight  Type of Clearance: None  Type of Airspace: Class G  Weather Information  Source of Briefing: Flight Service Station  Method of Briefing: In Person		35	1	35					+				+
Flight Plan/Itinerary Type of Flight Plan Filed: VFR  Departure Point State Airport Identifier Departure Time Time Zone AK PAFA 1400 AST  Destination State Airport Identifier Local Flight Type of Clearance: None Type of Airspace: Class G  Weather Information  Source of Briefing: Flight Service Station  Method of Briefing: In Person	Seatbelt Used? Yes	Shou	lder Harness	Used? Yes		Т	oxico	logy Perfo	rmed? N	lo		Second Pilot?	 ⁄es
Type of Flight Plan Filed: VFR  Departure Point Fairbanks AK PAFA 1400 AST  Destination Local Flight  Type of Clearance: None  Type of Airspace: Class G  Weather Information  Source of Briefing: Flight Service Station  Method of Briefing: In Person		I											
Type of Flight Plan Filed: VFR  Departure Point Fairbanks AK PAFA 1400 AST  Destination Local Flight  Type of Clearance: None  Type of Airspace: Class G  Weather Information  Source of Briefing: Flight Service Station  Method of Briefing: In Person	Flight Plan/Itinerary												
Fairbanks  AK PAFA  1400  AST  Destination Local Flight  Type of Clearance: None  Type of Airspace: Class G  Weather Information  Source of Briefing: Flight Service Station  Method of Briefing: In Person		/FR											
Fairbanks  AK PAFA  1400  AST  Destination Local Flight  Type of Clearance: None  Type of Airspace: Class G  Weather Information  Source of Briefing: Flight Service Station  Method of Briefing: In Person	Departure Point						State	Air	oort Ider	ntifier	Dep	arture Time	Time Zone
Local Flight  Type of Clearance: None  Type of Airspace: Class G  Weather Information  Source of Briefing: Flight Service Station  Method of Briefing: In Person	Fairbanks												
Local Flight  Type of Clearance: None  Type of Airspace: Class G  Weather Information  Source of Briefing: Flight Service Station  Method of Briefing: In Person	Destination						State Airport I		port Identifier				
Type of Airspace: Class G  Weather Information  Source of Briefing: Flight Service Station  Method of Briefing: In Person	- State / Amport to State.												
Weather Information  Source of Briefing: Flight Service Station  Method of Briefing: In Person	Type of Clearance: None												
Source of Briefing: Flight Service Station  Method of Briefing: In Person	Type of Airspace: Class G												
Flight Service Station  Method of Briefing: In Person	Weather Information												
FACTUAL REPORT - AVIATION Page 3	Method of Briefing: In Person												
	FACTUAL REPORT - AVIATION Page 3												

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC01LA037

Occurrence Date: 02/16/2001

Occurrence Type: Accident

	FTYBOR				71001001								
Weather Information													
WOF ID	Observation Time	Time Zone	WOF Elev	ation	WOF D	WOF Distance From Accident Site				Direction From Accident Site			
				Ft. MSL				NM		Deg. Mag.			
				FI. IVISL									
Sky/Lowes	st Cloud Condition: Sca	ttered				6000 Ft. A	GL	Condition o	Condition of Light: Day				
Lowest Ceiling: None					Visib	Visibility: 50				meter: "Hg			
Temperature: -7 °C Dew Point:					Wind Direction: Density Altitude:								
Wind Spee	ed: Calm	Gusts:		Weat	Weather Condtions at Accident Site: Visual Conditions								
Visibility (F	RVR): Ft.	Visibility (	RVV)	SM	Intensit	y of Precipit	tation:						
Restriction	s to Visibility: None												
Type of Pr	ecipitation: None												
Accident	Information												
Aircraft Da	Aircraft Damage: Aircraft Fire: Aircraft Explosion												
Classificat	Classification:												
- Injury Su	mmary Matrix	Fatal	Serious N	inor	None	TOTAL							
First P	ilot				1	1							
Secon	d Pilot												
Studer	t Pilot				1	1							
Flight I	nstructor												
Check	Pilot												
Flight E	Engineer												
Cabin A	Attendants												
Other (	Crew												
Passer	ngers												
- TOTAL ABOARD - 2 2													
Other (													
- GRANI	O TOTAL -				2	2	2						

National Transportation Safety Board

## FACTUAL REPORT AVIATION

NTSB ID: ANC01LA037

Occurrence Date: 02/16/2001

Occurrence Type: Accident

Δ	dm	inis	trativ	r⊵ Int	f∩rm	ation
$\overline{}$	ulli	บบอ	uauv			alioi

Investigator-In-Charge (IIC)

Scott Erickson

Additional Persons Participating in This Accident/Incident Investigation:

Jim Porter Air Safety Inspector FAA-AL-FAI FSDO 01 6450 Airport Way, Suite #2 Fairbanks, AK 99709